



Approved CR

IAA Milwaukee
N70W25277 Indian Grass Lane
Branch No 521
Sussex, WI 53089
(262) 246-8822/(262) 246-4411
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-450**
Bodystyle/Series: **Crew Cab XL**
Color: **Blue**
Mileage: **88,354
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT8W4DTXGEA23831**
Work Order/
Stock Number: **46360367**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G71A0878**
Vehicle Grade : **Grade 2.5**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 70 R 19

Car Tire Size - LR 225 / 70 R 19

Car Tire Size - RR 225 / 70 R 19

Car Tire Size - RF 225 / 70 R 19

LF Tires - 13/32 inch

LR Tires - 13/32 inch

RF Tires - 11/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - RR - G647 RSS

Tire Model - RF - G647 RSS

Tire Model - LR - G647 RSS

Tire Model - LF - G647 RSS

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Antenna	Aftermarket	-	Acceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Chipped	-	3
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Tailgate	Chipped	-	4
	Left Qtr Flare	Multiple Scratches Heavy	-	6
	Left Bed Side	Multiple Scratches Light	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Rear Door	Chipped	-	2
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	6
	Right Front Door	Peeling	-	> 12 Inches
	Right Rear Door	Peeling	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	9 To 10 Inches
	Right Qtr Flare	Multiple Scratches Light	-	3
	Right Rear Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.