



Approved CR

Dealers Auto Auction of Little Rock
4600 S University Ave
Little Rock , AR 72204
501-904-9988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 JEEP
GRAND
CHEROKEE**

Bodystyle/Series: **4 Door Sport
Utility
Vehicle
LAREDO E
4D SUV 4WD**

Color: **BLACK**

Mileage: **73,988
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1C4RJFAG5KC836908**

Work Order/
Stock Number: **000072901**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **GNO
PLATES**

Vehicle Grade : **Grade 4.5**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BEIGE	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	Power	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment


Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Automatic Headlights	Blind Spot Monitor
Bluetooth Connection	Brake Assist System	Car Tire Size - LF tire size P245/70SR17
Car Tire Size - LR tire size P245/70SR17	Car Tire Size - RF tire size P245/70SR17	Car Tire Size - RR tire size P245/70SR17
Child Safety Locks	Cruise Control	Cylinders - 6
Daytime Running Lights	Driver Air Bag	Empty Weight - 4625 lb
Engine Immobilizer	Floor Mats	Fog Lamps
Heated Front Seat(s)	Heated Mirrors	Heated Steering Wheel
Independent Climate Control	Intermittent Wipers	Keyless Entry
Keyless Start	LF Tires - 4/32 inch	LR Tires - 4/32 inch
Leather Steering Wheel	MP3 Radio	Master Key - 2key(s)
Motor Fuel Type - Gas	Pass-Through Rear Seat	Pass. Air Bag
Power Brakes	Power Driver Seat	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 4/32 inch	RR Tires - 4/32 inch
Rear Defrost	Rear Parking Aid	Rear Spoiler
Reverse Camera	Seat Trim - Cloth	Side Airbags - Front
Spare Tire	Steering Wheel Audio Control	Stereo - AM/FM Radio
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - Hood
Tire Brand - Front Left - LF tire mfg Nexen	Tire Brand - Front Right - RF tire mfg Nexen	Tire Brand - Rear Left - LR tire mfg Nexen
Tire Brand - Rear Right - RR tire mfg Nexen	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Aluminium
Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium
Woodgrain Interior Package		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Center Console	Hole(S)	Replace	1/8 To 1/2 Inch
	Front Bumper/Cover	Misaligned	Repair	Repair Required
	Front Bumper/Cover	Scuffed	Repair	10 To 11 Inches
[no photo]	Hood	Chipped	Repair	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.