



Approved
CR

United Auto Exchange
3710 Prescott Rd
Memphis, TN 38118
9017957634
jcraig@uaxmemphis.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021
HYUNDAI
ELANTRA
4 Door Sedan**

Bodystyle/Series: **SE 4D SEDAN
AT**

Color: **GRAY**

Mileage: **79,315
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **5NPLL4AG6MH048473**

Work Order/
Stock Number: **000082799**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G131936Y**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements:

- DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION
- HOWEVER, THE ABSENCE OF ANY INDICATED DEFICIENCIES
- DOES NOT MEAN THERE ARE NONE

Certification : **Not Certified**

Req. Prev. Repair
Order: **-**




Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
---------------	------------------------	------	-----

Equipment			
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	Automatic Headlights	
Blind Spot Monitor	Bluetooth Connection	Brake Assist System	
Car Tire Size - LF tire size 195/65R15	Car Tire Size - RR tire size 195/65R15	Car Tire Size - RF tire size 195/65R15	
Car Tire Size - LR tire size 195/65R15	Child Safety Locks	Collision Avoidance	
Cruise Control	Cylinders - 4	Daytime Running Lights	
Driver Air Bag	Empty Weight - 2868 lb	Floor Mats	
Front Wheel Drive	Front Wheel Drive	HD Radio	
Intermittent Wipers	Keyless Entry	LF Tires - 7/32 inch	
LR Tires - 5/32 inch	Lane Departure System	MP3 Radio	
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag	
Power Brakes	Power Lock	Power Mirrors	
Power Steering	Power Windows	RF Tires - 6/32 inch	
RR Tires - 8/32 inch	Rear Defrost	Remote Trunk Release	
Reverse Camera	Seat Trim - Cloth	Security System	
Side Airbags - Front	Spare Tire	Steering Wheel Audio Control	
Stereo - AM/FM Radio	Tilt Steering Wheel	Tilt Wheel	
Tire Brand - Front Left - LF tire mfg SAILUN	Tire Brand - Front Right - RF tire mfg SAILUN	Tire Brand - Rear Left - LR tire mfg SAILUN	
Tire Brand - Rear Right - RR tire mfg FIRESTONE	Tire Pressure Monitor System	Traction Control	
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Aluminium	
Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Dent(S) W/ Paint Dmg	Report	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Windshield	Star In Glass	Report	1 To 2 Inches
	Front Bumper Molding	Loose	Report	Repair Required
	Hood	Rust	Report	1/8 To 1/2 Inch
	Left Rear Door	Dent(S) W/ Paint Dmg	Report	1/2 To 1 Inch
	Right Qtr Panel	Multiple Dents/No Paint Damage	Report	2
	Right Front Door	Heavy Scratch	Report	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.