



Approved CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 FORD F-550 CHASSIS**
Bodystyle/Series: **Regular Cab XL**
Color: **White**
Mileage: **23,929 (Verified)**
Turn-in Mileage: **-**
VIN: **1FDUF5GY9FEA16858**
Work Order/ Stock Number: **46276994**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G710097X**
Vehicle Grade : **Grade 1.5**
Remarks: **-**
Announcements:

• RUST ON LIFTGATE AND REAR BODY PANEL

Certification : **-**
Req. Prev. Repair Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	10-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.8 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 70 R 19	Car Tire Size - LR 225 / 70 R 19	Car Tire Size - RR 225 / 70 R 19
Car Tire Size - RF 225 / 70 R 19	LF Tires - 12/32 inch	LR Tires - 11/32 inch
RF Tires - 12/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - DOUBLE COIN
Tire Brand - Front Right - DOUBLE COIN	Tire Brand - Rear Left - DOUBLE COIN	Tire Brand - Rear Right - DOUBLE COIN
Tire Model - RR - Double Coin RT600	Tire Model - RF - Double Coin RT600	Tire Model - LR - Double Coin RT600
Tire Model - LF - Double Coin RT600		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Running Board	Aftermarket	-	Acceptable
	Cargo Box	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Left Running Board	Aftermarket	-	Acceptable

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Tailgate	Rust	-	Severe Damage
	Left Front Wheel	Corrosion	-	> 12 Inches
	Right Front Seat Cushion	Torn	-	1 To 2 Inches
	Left Front Seat Cushion	Torn	-	7 To 8 Inches
	Left Front Seat Bolster	Torn	-	4 To 5 Inches
	Exterior Rear Body Panel	Rust	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Front Wheel	Corrosion	-	> 12 Inches
	Cargo Box Right Side Wall	Multiple Dents/Paint Damage	-	2
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Lift Gate	Peeling	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.