Approved CR

IAA High Desert
11385 G Avenue
Branch No 133
Hesperia, CA 92345
(760)949-8404/(760)949-0400
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2019 FORD F-250**
Bodystyle/Series:	**Regular Cab XL**
Color:	**White**
Mileage:	**45,022 (Verified)**
Turn-in Mileage:	-
VIN:	**1FDBF2A65KEC15736**
Work Order/ Stock Number:	**46417262**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G432591V**
Vehicle Grade :	**Grade 3.5**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Carriage**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 10/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - HERCULES
Tire Brand - Front Right - HERCULES	Tire Brand - Rear Left - HERCULES	Tire Brand - Rear Right - HERCULES
Tire Model - LR - Terra Trac CH4	Tire Model - LF - Terra Trac CH4	Tire Model - RR - Terra Trac CH4
Tire Model - RF - Terra Trac CH4		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Front Metal Bumper Painted	Heavy Scratch	-	9 To 10 Inches
	Right Side Panel	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Heavy Scratch	-	> 12 Inches
	Right Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Steering Wheel	Worn	-	Replacement Required
	Right Front Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.