Approved CR

IAA Milwaukee
N70W25277 Indian Grass Lane
Branch No 521
Sussex, WI 53089
(262) 246-8822/(262) 246-4411
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 FORD FUSION HYBRID**
Bodystyle/Series:	**4 Door Sedan SE**
Color:	**Black**
Mileage:	**82,699 (Verified)**
Turn-in Mileage:	-
VIN:	**3FA6P0LU4KR274685**
Work Order/ Stock Number:	**46482430**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G102514W**
Vehicle Grade :	**Grade 4.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 50 R 17	Car Tire Size - LR 225 / 50 R 17	Car Tire Size - RR 225 / 50 R 17
Car Tire Size - RF 225 / 50 R 17	LF Tires - 10/32 inch	LR Tires - 7/32 inch
RF Tires - 11/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - UNIROYAL
Tire Brand - Front Right - UNIROYAL	Tire Brand - Rear Left - UNIROYAL	Tire Brand - Rear Right - UNIROYAL
Tire Model - RR - Tiger Paw Touring	Tire Model - RF - Tiger Paw Touring	Tire Model - LR - Tiger Paw Touring
Tire Model - LF - Tiger Paw Touring		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Chipped	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	1 To 2 Inches
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Right Front Fender	Chipped	-	2
	Hood	Chipped	-	3
	Left Drip Rail	Chipped	-	3
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.