



Approved CR

IAA Eugene
1000 Bethel Drive
Branch No 309
Eugene, OR 97402
(541) 689-4000/(541) 689-0083
WHOLESALE ASSESSMENT ONLY

Make/Model: **2010 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **Silver**

Mileage: **123,161
(Verified)**

Turn-in Mileage: **-**

VIN: **2D4RN4DE6AR111541**

Work Order/
Stock Number: **46310666**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G41B5563**

Vehicle Grade : **Grade 3.0**

Remarks: **-**



Announcements:

• REPAIRS
MAY BE
NEEDED

• NON GSA
OWNED
VEHICLE

• PARTS MAY
BE MISSING

• REPAIR
HISTORY
NOT
AVAILABLE.
CONDITION
UNKNOWN

Certification : **-**

Req. Prev. Repair **-**

Order: **-**

Drivable: Yes

Equipment

Transmission:	Automatic Transmission w/ Overdrive	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.3 L	Pwr Steering:	Yes

Equipment

Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /SILVER	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Additional Equipment:

Car Tire Size - LF 225 / 65 R 16	Car Tire Size - LR 225 / 65 R 16	Car Tire Size - RR 225 / 65 R 16
Car Tire Size - RF 225 / 65 R 16	LF Tires - 7/32 inch	LR Tires - 8/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - TOYO
Tire Brand - Front Right - TOYO	Tire Brand - Rear Left - TOYO	Tire Brand - Rear Right - TOYO
Tire Model - RR - Ultra Z900	Tire Model - RF - Ultra Z900	Tire Model - LR - Ultra Z900
Tire Model - LF - Ultra Z900		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required
	Right Rear Wheel Cover	Broken	-	Replacement Required
	Right Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Curb Rash	-	1 To 2 Inches
	Windshield	Multiple Chips	-	10 Or More
	Steering Wheel	Worn	-	Replacement Required
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Rear Door Molding	Peeling	-	9 To 10 Inches
	Front Bumper	Scraped	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Multiple Scratches Heavy	-	5
	Left Qtr Panel	Heavy Scratch	-	1/2 To 1 Inch
	Right Rear Door	Multiple Dents/Paint Damage	-	3
	Right Front Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.