



Approved CR

IAA Billings
75 Cerise Road
Branch No 361
Billings, MT 59101
(406) 259-2377/(406) 259-2302
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
CHEVROLET
SILVERADO
2500HD**

Bodystyle/Series: **- WT**

Color: **White**

Mileage: **37,952
(Verified)**

Turn-in Mileage: **-**

VIN: **2GC2KREG7K1191260**

Work Order/
Stock Number: **46296684**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G63-0940W**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Synthetic Leather /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 70 R 17

Car Tire Size - LR 265 / 70 R 17

Car Tire Size - RR 265 / 70 R 17

Car Tire Size - RF 265 / 70 R 17

LF Tires - 8/32 inch

LR Tires - 11/32 inch

RF Tires - 9/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - HANKOOK

Tire Brand - Front Right - HANKOOK

Tire Brand - Rear Left - HANKOOK

Tire Brand - Rear Right - HANKOOK

Tire Model - RR - Dynapro AT2 Xtreme
RF12

Tire Model - RF - Dynapro AT2 Xtreme
RF12

Tire Model - LR - Dynapro AT2 Xtreme
RF12

Tire Model - LF - Dynapro AT2 Xtreme
RF12

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Mud Guard	Loose	-	Repair Required
	Fifth Wheel Trailer Hitch	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	2 To 3 Inches
	Left Front Seat Cushion	Torn	-	1 To 2 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Chipped	-	3
	Tailgate	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Right Bed Side	Chipped	-	2
	Right Front Door	Chipped	-	2
	Right Front Wheel	Corrosion	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.