Approved CR

Carriage Trade Auto Auction
1200 Ridge Pike
Conshohocken, PA 19428
215-CAR-SALE/(610) 834-8274
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 DODGE CHARGER**
Bodystyle/Series:	**4 Door Vehicle SXT**
Color:	**SILVER**
Mileage:	**53,607 (Digital)**
Turn-in Mileage:	-
VIN:	**2C3CDXJG8LH186848**
Work Order/ Stock Number:	**0182397**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G115706Q**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	• Previous police vehicle • PRIOR POLICE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment


Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**All Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Automatic Headlights	Auxiliary Audio Input	Backup camera and monitor
Bluetooth Connection	Brake Assist System	Car LF Tires - 5/32 inch
Car LR Tires - 3/32 inch	Car RF Tires - 5/32 inch	Car RR Tires - 3/32 inch
Car Tire Size - LF: P235/55HR19 LR: P235/55HR19 RF: P235/55HR19 RR: P235/55HR19 SP: SPACE SAVER	Child Safety Locks	Cylinders - 6
Daytime Running Lights	Driver Adjustable Lumbar	Driver Illuminated Vanity Mirr
Driver Vanity Mirror	Electrochromic Rearview Mirror	Electronic Stability Control
Engine Immobilizer	Floor Mats	Fog Lamps
Front Head Air Bag	HD Radio	Heated Mirrors
Ignition Key - 1key(s)	Independent Climate Control	Intermittent Wipers
Keyless Entry - Left	Keyless Start	Knee Air Bag
LF Tires - 5/32 inch	LR Tires - 3/32 inch	Leather Steering Wheel
MP3 Radio	Pass-Through Rear Seat	Pass. Air Bag
Passenger Air Bag Sensor	Passenger Illuminated Vanity M	Passenger Vanity Mirror
Power Driver Seat	Power Mirrors	Premium Stereo
RF Tires - 5/32 inch	RR Tires - 3/32 inch	Rear Bench Seat
Rear Head Air Bag	Rear Parking Aid	Rear Spoiler
Remote Trunk Release	Side Airbags - Front	Smart Device Integration
Spare Tire - Space Saver	Spare Tire Tread - 3/32 inch	Spare Wheel - Steel
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire LF - 5/32 inch	Tire Pressure Monitor System	Tire RF - 5/32 inch
Tire Size - LF: P235/55HR19 LR: P235/55HR19 RF: P235/55HR19 RR: P235/55HR19 SP: SPACE SAVER	Tire Size - LF: P235/55HR19 LR: P235/55HR19 RF: P235/55HR19 RR: P235/55HR19 SP: SPACE SAVER	Transmission - Automatic Transmission
Trip Computer	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	WiFi Hotspot
XM Radio		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Front Bumper	Multiple Scratches Light	Estimate Only	4
[no photo]	Hood	Chipped	Estimate Only	3
[no photo]	Left Rear Door	Multiple Scratches Light	Estimate Only	4
[no photo]	Deck Lid	Multiple Scratches Light	Estimate Only	4
[no photo]	Right Rear Door	Multiple Scratches Light	Estimate Only	3
[no photo]	Right Qtr Panel	Multiple Scratches Light	-	2
	Right Front Fender	Dent(S) W/No Paint Dmg	Estimate Only	2 To 3 Inches
	Digital Display	Photo Only	Remove	None
	Rf Floor Panel	Hole(S)	Estimate Only	3 To 4 Inches
	Luggage Carpeting	Hole(S)	Estimate Only	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.