Approved CR

IAA Providence
160 Amaral St
Branch No 644
Riverside, RI 02915
(401) 438-5254/(401) 438-3523
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 HYUNDAI ELANTRA**
Bodystyle/Series:	**4 Door Sedan SE**
Color:	**Black**
Mileage:	**29,824 (Verified)**
Turn-in Mileage:	-
VIN:	**5NPD74LF9KH476404**
Work Order/ Stock Number:	**46468889**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G130069W**
Vehicle Grade :	**Grade 3.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15	Car Tire Size - LR 195 / 65 R 15	Car Tire Size - RR 195 / 65 R 15
Car Tire Size - RF 195 / 65 R 15	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 6/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - KUMHO
Tire Brand - Front Right - KUMHO	Tire Brand - Rear Left - KUMHO	Tire Brand - Rear Right - KUMHO
Tire Model - LF - Solus TA31	Tire Model - RF - Solus TA31	Tire Model - RR - Solus TA31
Tire Model - LR - Solus TA31		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door Handle	Chipped	-	1
	Left Front Door	Multiple Scratches Heavy	-	10 Or More
	Right Front Door	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Chipped	-	1
	Left Rear Door	Multiple Scratches Heavy	-	2
	Left Qtr Panel	Multiple Scratches Heavy	-	3
	Front Bumper	Multiple Scratches Heavy	-	2
	Overall Vehicle	De-Identify	-	Removal Required
	Rear Bumper Cover Upper	Multiple Scratches Heavy	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.