



Approved CR

IAA Tifton
368 Oak Ridge Church Rd
Branch No 703
Tifton, GA 31794
(229) 386-2640/(229) 386-2650
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 DODGE
DURANGO**
Bodystyle/Series: **Sport Utility
Vehicle
PURSUIT
AWD**
Color: **White**
Mileage: **72,299
(Verified)**
Turn-in Mileage: **-**
VIN: **1C4RDJFG6LC369504**
Work Order/
Stock Number: **46367980**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G621769X**
Vehicle Grade : **Grade 3.7**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes



Equipment

Additional Equipment:

Car Tire Size - RR 262 / 60 R 18	Car Tire Size - RF 262 / 60 R 18	Car Tire Size - LF 262 / 60 R 18
Car Tire Size - LR 262 / 60 R 18	LF Tires - 9/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - NITTO
Tire Brand - Front Right - NITTO	Tire Brand - Rear Left - HEMISPHERE	Tire Brand - Rear Right - HEMISPHERE
Tire Model - LF - Crosstek 2	Tire Model - LR - Aethon 4X4 HP	Tire Model - RF - Crosstek 2
Tire Model - RR - Aethon 4X4 HP		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Left Front Seat Cushion	Torn	-	3 To 4 Inches
	Left Front Door Panel	Gouged	-	< 1/8 Inch
	Overall Vehicle	De-Identify	-	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.