



Approved CR

IAA Raleigh  
60 Sadisco Road  
Branch No 747  
Clayton, NC 27520  
(919) 553-6148/(919) 553-2857  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM  
2500**  
Bodystyle/Series: **Crew Cab  
TRADESMAN  
4X4 8' BOX**  
Color: **Gray**  
Mileage: **38,780  
(Verified)**  
Turn-in Mileage: **-**  
VIN: **3C6TR5HT5JG300703**  
Work Order/  
Stock Number: **46368139**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**  
Client Stock #: **G631432V**  
Vehicle Grade : **Grade 2.4**  
Remarks: **-**  
Announcements: **-**  
Certification : **-**  
Req. Prev. Repair **-**  
Order: **-**



Drivable: Yes

### Equipment

|                        |                                |                 |                      |
|------------------------|--------------------------------|-----------------|----------------------|
| Transmission:          | <b>Automatic Transmission</b>  | A/C:            | <b>No</b>            |
| Engine:                | <b>8-Cylinder Gas</b>          | Cruise Control: | <b>Yes</b>           |
| Engine Size:           | <b>5.7 L</b>                   | Pwr Steering:   | <b>Yes</b>           |
| Roof:                  | <b>Hard Top</b>                | Pwr Locks:      | <b>Yes</b>           |
| Radio:                 | <b>-</b>                       | Pwr Windows     | <b>Yes</b>           |
| Interior - Type/Color: | <b>Synthetic Leather /GRAY</b> | Rear Defroster: | <b>Yes</b>           |
| Airbag:                | <b>Driver Side Air Bag</b>     | Tilt Steering:  | <b>Yes</b>           |
| Seats:                 | <b>Bench</b>                   | Drive Type:     | <b>4-Wheel Drive</b> |
| Seat Count:            | <b>-</b>                       | Brakes:         | <b>Disc</b>          |

## Equipment

### Additional Equipment:

Car Tire Size - LF 245 / 70 R 17

Car Tire Size - LR 245 / 70 R 17

Car Tire Size - RR 245 / 70 R 17

Car Tire Size - RF 245 / 70 R 17

LF Tires - 9/32 inch

LR Tires - 8/32 inch

RF Tires - 9/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Transforce HT2

Tire Model - RF - Transforce HT2

Tire Model - LR - Transforce HT2

Tire Model - LF - Transforce HT2

## Non Chargeable Damages

| Photo                                                                               | Item                       | Damage     | Action | Severity     |
|-------------------------------------------------------------------------------------|----------------------------|------------|--------|--------------|
|    | Warning - Traction Control | On         | -      | Unacceptable |
|   | Warning Light - Abs        | On         | -      | Unacceptable |
|  | Photo - Vin/Id Sticker     | Photo Only | -      | -            |
|  | Engine                     | Photo Only | -      | -            |
|  | Keys                       | Photo Only | -      | -            |
|  | Right Side Panel           | Photo Only | -      | -            |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Left Side Panel         | Photo Only | -      | -        |
|    | Instrument Panel        | Photo Only | -      | -        |
|    | Rear Bumper             | Photo Only | -      | -        |
|    | Extra Photo 2           | Photo Only | -      | -        |
|    | Extra Photo 3           | Photo Only | -      | -        |
|   | Right Front Fender      | Photo Only | -      | -        |
|  | Extra Photo 4           | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item               | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|--------------------|------------|--------|----------|
|  | Front Cover Center | Photo Only | -      | -        |
|  | Extra Photo 1      | Photo Only | -      | -        |
|  | Odometer           | Photo Only | -      | -        |
|  | Rear Seats         | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item                      | Damage                      | Action | Severity       |
|-------------------------------------------------------------------------------------|---------------------------|-----------------------------|--------|----------------|
|   | Right Rear Wheel          | Corrosion                   | -      | 1/2 To 1 Inch  |
|  | Tailgate                  | Multiple Dents/Paint Damage | -      | 2              |
|  | Rear Metal Bumper Painted | Dent(S) W/ Paint Dmg        | -      | 9 To 10 Inches |

### Chargeable Damages

| Photo                                                                               | Item                       | Damage                   | Action | Severity      |
|-------------------------------------------------------------------------------------|----------------------------|--------------------------|--------|---------------|
|    | Left Bed Side              | Chipped                  | -      | 4             |
|    | Left Rear Wheel            | Corrosion                | -      | 1/2 To 1 Inch |
|    | Left Front Wheel           | Corrosion                | -      | 1/2 To 1 Inch |
|   | Right Rear Door            | Dent(S) W/No Paint Dmg   | -      | 1/2 To 1 Inch |
|  | Left Rocker Panel          | Scraped                  | -      | 5 To 6 Inches |
|  | Front Metal Bumper Painted | Multiple Scratches Heavy | -      | 3             |

| Chargeable Damages                                                                 |                   |                        |        |               |
|------------------------------------------------------------------------------------|-------------------|------------------------|--------|---------------|
| Photo                                                                              | Item              | Damage                 | Action | Severity      |
|   | Hood              | Chipped                | -      | 3             |
|   | Right Front Wheel | Curb Rash              | -      | 1 To 2 Inches |
|   | Right Cab Side    | Heavy Scratch          | -      | 1 To 2 Inches |
|  | Right Bed Side    | Dent(S) W/No Paint Dmg | -      | 1/2 To 1 Inch |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.