Approved CR

IAA Columbus
1601 Thrailkill Road
Branch No 662
Grove City, OH 43123
(614) 875-7484/(614) 875-7277
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 DODGE GRAND CARAVAN**
Bodystyle/Series:	**Van SE**
Color:	**Blue**
Mileage:	**15,991 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RDGBG8JR254870**
Work Order/ Stock Number:	**46484843**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G410816V**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17	Car Tire Size - LR 225 / 65 R 17	Car Tire Size - RR 225 / 65 R 17
Car Tire Size - RF 225 / 65 R 17	LF Tires - 7/32 inch	LR Tires - 10/32 inch
RF Tires - 7/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - MASTERCRAFT
Tire Brand - Front Right - MASTERCRAFT	Tire Brand - Rear Left - KUMHO	Tire Brand - Rear Right - KUMHO
Tire Model - RR - Solus KH16	Tire Model - RF - Stratus As	Tire Model - LR - Solus KH16
Tire Model - LF - Stratus As		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel Cover	Peeling	-	9 To 10 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Lift Gate	Chipped	-	3
	Right Rear Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.