Approved CR

IAA Fresno
1805 N Lafayette Ave
Branch No 337
Fresno, CA 93705
(559) 264-5033 /(559) 264-4251
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2023 CHRYSLER PACIFICA HYBRID**
Bodystyle/Series:	**Van TOURING L**
Color:	**Black**
Mileage:	**100,877 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RC1L76PR541812**
Work Order/ Stock Number:	**46485024**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G410459Z**
Vehicle Grade :	**Grade 3.9**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**6-Cylinder Hybrid**	Cruise Control:	**No**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Leather Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 65 R 17	Car Tire Size - RF 235 / 65 R 17	Car Tire Size - LF 235 / 65 R 17
Car Tire Size - LR 235 / 65 R 17	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - caldera tires
Tire Brand - Front Right - caldera tires	Tire Brand - Rear Left - caldera tires	Tire Brand - Rear Right - caldera tires
Tire Model - LF - confidence lt-s	Tire Model - LR - confidence lt-s	Tire Model - RF - confidence lt-s
Tire Model - RR - confidence lt-s		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	3
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Right Qtr Panel	Chipped	-	2
	Rear Bumper	Multiple Scratches Heavy	-	8
	Right Qtr Panel	Heavy Scratch	-	4 To 5 Inches
	Right Front Fender	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.