



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 BLUE
BIRD
SCHOOL
BUS / TRANS**

Bodystyle/Series: **Bus -**

Color: **WHITE**

Mileage: **86,297
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1BAKGCPA7FF310506**

Work Order/
Stock Number: **000354971**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G32A0363**

Vehicle Grade : **Grade 2.0**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	No
Engine Size:	6.7 L	Pwr Steering:	No
Roof:	Hard Top	Pwr Locks:	No
Radio:	AM/FM CD	Pwr Windows	No
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

CD Player	Car Tire Size - LR TIRE SIZE 11R22.5	Car Tire Size - RF TIRE SIZE 11R22.5
Car Tire Size - RR TIRE SIZE 11R22.5	Car Tire Size - LF TIRE SIZE 11R22.5	LF Tires - 14/32 inch
LR Tires - 10/32 inch	RF Tires - 14/32 inch	RR Tires - 8/32 inch
Tire Brand - Front Left - LF TIRE MFG Toyo	Tire Brand - Front Right - RF TIRE MFG Toyo	Tire Brand - Rear Left - LR TIRE MFG Sumitomo
Tire Brand - Rear Right - RR TIRE MFG Sumitomo	Two-Wheel Drive	

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Left	Photo Only	Estimate Only	Unknown
	Miscellaneous	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Engine	Additional Damage	Report	Unknown
[no photo]	Warning Light - Engine	On	Report	Unknown
	Cab - Interior Left	Additional Damage	Report	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Peeling	Report	Unknown
	Front Ls Panel	Multiple Scratches Heavy	Report	Unknown
	Hood	Gouged	Report	Unknown
	Left Head Lamp	Oxidized	Report	Unknown
	Left Qtr Panel	Multiple Dents/Paint Damage	Report	Unknown
	Left Front Fender	Peeling	Report	Unknown
	Left Front Seat	Worn	Report	Unknown
	Overall Exterior	Oxidized	Report	Unknown
	Right Bed Side	Multiple Dents/Paint Damage	Report	Unknown
	Right Head Lamp	Oxidized	Report	Unknown
	Right Qtr Panel	Additional Damage	Report	Unknown
	Rear Bumper	Additional Damage	Report	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Sunvisor	Broken	Report	Unknown
	Right Front Door	Peeling	Report	Unknown
	Seats	Additional Damage	Report	Unknown
	Sunroof Shade	Additional Damage	Report	Unknown
[no photo]	Battery	Dead	Report	Unknown
[no photo]	A/C/Heat Register	Additional Damage	Report	Unknown

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.