



Approved
CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT-150**
Bodystyle/Series: **Cargo Van -**
Color: **White**
Mileage: **12,456 (Verified)**
Turn-in Mileage: **-**
VIN: **1FTYE1YM2JKB31194**
Work Order/
Stock Number: **46358739**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G433248V**
Vehicle Grade : **Grade 3.7**
Remarks: **-**
Announcements:

• ANNOUNCEMENTS:
Corrosion

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 16

Car Tire Size - LR 235 / 65 R 16

Car Tire Size - RR 235 / 65 R 16

Car Tire Size - RF 235 / 65 R 16

LF Tires - 11/32 inch

LR Tires - 11/32 inch

RF Tires - 11/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - SAILUN

Tire Brand - Front Right - SAILUN

Tire Brand - Rear Left - SAILUN

Tire Brand - Rear Right - SAILUN

Tire Model - RR - Terramax HLT

Tire Model - RF - Terramax HLT

Tire Model - LR - Terramax HLT

Tire Model - LF - Terramax HLT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Cargo Shelf	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Chipped	-	2
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Front Wheel	Corrosion	-	> 12 Inches
	Rear Ls Panel	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Rear Door Cladding	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.