Approved CR

Mid Kansas Auto Auction Wichita
4716 S. Santa Fe
Wichita , KS 67216
316-500-7700/316-500-7701
codyd@mksaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2021 RAM 3500 Crew Cab**
Bodystyle/Series:	**TRADESMAN CREW CAB 4WD SWB SRW**
Color:	**WHITE**
Mileage:	**68,729 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**3C63R3CJ6MG665700**
Work Order/ Stock Number:	**000115035**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G63-0270Y**
Vehicle Grade :	**Grade 2.6**
AutoGrade :	**2.6 - Below Average**
Remarks:	-
Announcements:	• (O) Hail Damage • (O) Engine has tick. Repairs and/or parts may be necessary. • (A)-ail Damage
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.4 L**	Pwr Steering:	**Yes**


Equipment

Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**


Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Automatic Headlights	Bluetooth Connection
Brake Assist System	Car Tire Size - RF tire size LT275/70SR18	Car Tire Size - LR tire size LT275/70SR18
Car Tire Size - LF tire size LT275/70SR18	Car Tire Size - RR tire size LT275/70SR18	Child Safety Locks
Cruise Control	Cylinders - 8	Daytime Running Lights
Driver Air Bag	Engine Immobilizer	Floor Mats
Heated Mirrors	Intermittent Wipers	Keyless Entry
Keyless Start	LF Tires - 7/32 inch	LR Tires - 10/32 inch
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Gas
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 6/32 inch	RR Tires - 10/32 inch
Rear Defrost	Reverse Camera	Running Board
Seat Trim - Vinyl	Side Airbags - Front	Spare Tire
Stereo - AM/FM Radio	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Firestone
Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone	Tire Brand - Rear Right - RR tire mfg Firestone
Tire Pressure Monitor System	Tow Hitch	Traction Control
Transmission - Automatic Transmission	Turn Signal Mirrors	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Hail Damage	PDR	10 Or More
	Left Bed Side	Multiple Dents/No Paint Damage	PDR	10 Or More
	Left Rocker Panel	Multiple Scratches Heavy	Touch Up	3
	L Cab Corner Panel	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Front Door	Chipped	Touch Up	3
	Left Front Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Front Fender	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Right Bed Side	Multiple Dents/No Paint Damage	PDR	10 Or More
	Rear Metal Bumper Painted	Severe Damage	Replace	Replacement Required
	Roof	Multiple Dents/No Paint Damage	PDR	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Chipped	Touch Up	3
	Right Front Fender	Multiple Scratches Light	Report	6
	Right Rear Door	Multiple Scratches Light	Report	3
	Tailgate	Multiple Dents/No Paint Damage	PDR	Pdr-3 Dents

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.