



Approved
CR

IAA Lincoln
301 Madigan Dr
Branch No 509
Lincoln, IL 62656
(217) 732-8555/(217) 732-7555
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **Blue**

Mileage: **80,293 (Verified)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG1KR679297**

Work Order/
Stock Number: **46369241**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G411932W**

Vehicle Grade : **Grade 3.6**

Remarks: **-**

Announcements:

**• HOOD
CORROSION/RUST**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment



Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment


Additional Equipment:

Car Tire Size - LF 225 / 65 R 17	Car Tire Size - LR 225 / 65 R 17	Car Tire Size - RR 225 / 65 R 17
Car Tire Size - RF 225 / 65 R 17	LF Tires - 2/32 inch	LR Tires - 7/32 inch
RF Tires - 2/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - MICHELIN
Tire Brand - Front Right - MICHELIN	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - RR - Energy Saver A/S	Tire Model - RF - Energy Saver A/S	Tire Model - LR - Energy Saver A/S
Tire Model - LF - Energy Saver A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Rust	-	9 To 10 Inches
	Left Front Tire	Worn	-	Replacement Required
	Right Front Tire	Worn	-	Replacement Required
	Front Bumper	Chipped	-	3
	Right Rear Wheel Cover	Curb Rash	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.