



Approved CR

IAA Seattle  
15801 110th Ave E  
Branch No 327  
Puyallup, WA 98374  
(253)604-2300/(253)604-2390  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018  
HYUNDAI  
IONIQ  
HYBRID**

Bodystyle/Series: **4 Door Hatch  
Back BLUE**

Color: **Black**

Mileage: **47,430  
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC9JU075767**

Work Order/  
Stock Number: **46323724**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalessupport@gsa.gov**

Client Stock #: **G131763V**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                       |                 |                   |
|------------------------|-----------------------|-----------------|-------------------|
| Transmission:          | -                     | A/C:            | No                |
| Engine:                | 4-Cylinder Hybrid     | Cruise Control: | Yes               |
| Engine Size:           | 1.6 L                 | Pwr Steering:   | Yes               |
| Roof:                  | Hard Top              | Pwr Locks:      | Yes               |
| Radio:                 | -                     | Pwr Windows     | Yes               |
| Interior - Type/Color: | Cloth Interior /BLACK | Rear Defroster: | Yes               |
| Airbag:                | Driver Side Air Bag   | Tilt Steering:  | Yes               |
| Seats:                 | 3rd                   | Drive Type:     | Front Wheel Drive |
| Seat Count:            | -                     | Brakes:         | Disc              |

## Equipment

### Additional Equipment:

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

LF Tires - 5/32 inch

LR Tires - 8/32 inch

RF Tires - 5/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - MICHELIN

Tire Brand - Front Right - DEAN

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - LF - Energy Saver A/S

Tire Model - LR - Energy Saver

Tire Model - RF - ROAD CONTROL

Tire Model - RR - Energy Saver

## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity   |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|------------|
|    | Steering Wheel         | Worn       | -      | Acceptable |
|   | Photo - Vin/Id Sticker | Photo Only | -      | -          |
|  | Engine                 | Photo Only | -      | -          |
|  | Keys                   | Photo Only | -      | -          |
|  | Front Cover Center     | Photo Only | -      | -          |
|  | Right Side Panel       | Photo Only | -      | -          |
|  | Left Side Panel        | Photo Only | -      | -          |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Instrument Panel        | Photo Only | -      | -        |
|    | Rear Bumper             | Photo Only | -      | -        |
|    | Right Front Fender      | Photo Only | -      | -        |
|    | Left Front Fender       | Photo Only | -      | -        |
|    | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|   | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |
|  | Odometer                | Photo Only | -      | -        |
|  | Rear Seats              | Photo Only | -      | -        |

| Chargeable Damages                                                                  |                         |                          |        |               |
|-------------------------------------------------------------------------------------|-------------------------|--------------------------|--------|---------------|
| Photo                                                                               | Item                    | Damage                   | Action | Severity      |
|    | Front Bumper            | Multiple Scratches Heavy | -      | 2             |
|    | Right Front Wheel Cover | Curb Rash                | -      | 1 To 2 Inches |
|    | Left Rear Wheel Cover   | Curb Rash                | -      | 1/2 To 1 Inch |
|   | Left Front Door         | Chipped                  | -      | 2             |
|  | Left Front Wheel Cover  | Curb Rash                | -      | 1 To 2 Inches |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.