



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017
CHEVROLET
EXPRESS
PASSENGER**

Bodystyle/Series: **Van LS
WAGON**

Color: **WHITE**

Mileage: **7,577
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1GAWGEFF3H1267601**

Work Order/
Stock Number: **000355625**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G431034U**

Vehicle Grade : **Grade 4.3**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.8 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	No
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment


Additional Equipment:

3rd Row Seat	ABS Brakes	Air Conditioning
Auxiliary Pwr Outlet	Bluetooth Connection	CD Player
Car Tire Size - RR tire size LT245/75R16E	Car Tire Size - RF tire size LT245/75R16E	Car Tire Size - LF tire size LT245/75R16E
Car Tire Size - LR tire size LT245/75R16E	Cruise Control	Cylinders - 8
Daytime Running Lights	Driver Air Bag	Engine Immobilizer
Front Reading Lamps	Intermittent Wipers	LF Tires - 13/32 inch
LR Tires - 13/32 inch	Leather Steering Wheel	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass-Through Rear Seat
Pass. Air Bag	Power Brakes	Power Lock
Power Steering	Privacy Glass	RF Tires - 13/32 inch
RR Tires - 13/32 inch	Rear AC	Rear View Mirror
Reverse Camera	Seat Trim - Cloth	Side Airbags - Front
Spare Tire	Steering Wheel Audio Control	Stereo - AM/FM Radio
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Generic	Tire Brand - Front Right - RF tire mfg Generic
Tire Brand - Rear Left - LR tire mfg Generic	Tire Brand - Rear Right - RR tire mfg Generic	Tire Pressure Monitor System
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Trip Computer
Two-Wheel Drive	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	XM Radio

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown




Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Cargo Door	Multiple Scratches Light	Report	4
	Right Rear Cargo Door	Multiple Scratches Light	Report	6
	Hood	Multiple Dents/No Paint Damage	Report	3
	Cab - Left	Chipped	Report	3
	Left Qtr Panel	Multiple Scratches Light	Report	6
	Left Front Door	Multiple Scratches Light	Report	4
	Left Front Fender	Multiple Scratches Light	Report	4

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Chipped	Report	3
	Right Front Door	Multiple Scratches Light	Report	6
	Right Rear Door	Multiple Scratches Light	Report	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.