Approved CR

America`s Auto Auction - Richmond
3600 Deepwater Terminal Road
Richmond, VA 23234
804-232-7355/804-232-1818
richmond.fleet@americasaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2007 JEEP GRAND CHEROKEE**
Bodystyle/Series:	**4 Door Sport Utility Vehicle LAREDO 4D SUV 4WD**
Color:	**BLUE**
Mileage:	**29,290 (Exempt, 6 digits)**
Turn-in Mileage:	-
VIN:	**1J8HR48P87C631033**
Work Order/ Stock Number:	**000845474**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G61C8818**
Vehicle Grade :	**Grade 4.5**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**4.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM CD**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Auxiliary Pwr Outlet	Brake Assist System
CD Player	Car Tire Size - RF tire size P245/65R17	Car Tire Size - RR tire size P245/65R17
Car Tire Size - LF tire size P245/65R17	Car Tire Size - LR tire size P245/65R17	Cruise Control
Cylinders - 8	Daytime Running Lights	Driver Air Bag
Engine Immobilizer	Floor Mats	Intermittent Wipers
Keyless Entry	LF Tires - 7/32 inch	LR Tires - 9/32 inch
Master Key - 1key(s)	Motor Fuel Type - Other	Pass-Through Rear Seat
Pass. Air Bag	Power Brakes	Power Driver Seat
Power Lock	Power Mirrors	Power Steering
Power Windows	Privacy Glass	RF Tires - 7/32 inch
RR Tires - 9/32 inch	Rear Defrost	Rear Reading Lamps
Seat Trim - Cloth	Spare Tire	Stereo - AM/FM Radio
Tilt Steering Wheel	Tire Pressure Monitor System	Tow Hitch
Traction Control	Transmission - Automatic Transmission	Trip Computer
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lift Gate	Heavy Scratch	Repair	3 To 4 Inches
	Left Front Door	Heavy Scratch	Repair	1/2 To 1 Inch
	Left Front Fender	Heavy Scratch	Repair	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.