



Approved CR

IAA Appleton
2591 S Casaloma Drive
Branch No 522
Appleton, WI 54914
(920) 734-1446/(920) 734-3603
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 FORD
F-150**

Bodystyle/Series: **- XLT**

Color: **Black**

Mileage: **91,503
(Verified)**

Turn-in Mileage: **-**

VIN: **1FTEW1EP1PKD19339**

Work Order/
Stock Number: **46232831**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G625366Z**

Vehicle Grade : **Grade 2.8**

Remarks: **-**

Announcements:

**• WARNING
LIGHT
INDICATOR
ON**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Traction Control

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17

Car Tire Size - LF 265 / 70 R 17

Car Tire Size - RF 265 / 70 R 17

Car Tire Size - LR 265 / 70 R 17

LF Tires - 4/32 inch

LR Tires - 6/32 inch

RF Tires - 4/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR


Tire Model - RR - Wrangler At/S

Tire Model - RF - Wrangler At/S




Tire Model - LR - Wrangler At/S

Tire Model - LF - Wrangler At/S

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning - Blind Spot Monitor	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Hood	Chipped	-	3
	Roof	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Ignition	Broken	-	Replacement Required
	Right Bed Side	Multiple Scratches Heavy	-	2
	Left Bed Side	Multiple Scratches Heavy	-	3
	Tailgate Protective Cap	Gouged	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.