



Approved
CR

Akron Auto Auction
2471 Ley Drive
Akron, OH 44319
3304365819/(330) 773-3921
lbeth@akronautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
HYUNDAI
IONIQ
HYBRID
4 Door Sedan**

Bodystyle/Series: **BLUE 4D
HATCHBACK**

Color: **BLACK**

Mileage: **53,532
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **KMHC65LC0JU075253**

Work Order/
Stock Number: **000845646**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G130981V**

Vehicle Grade : **Grade 2.8**

AutoGrade : **2.8 - Below
Average**


Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive


Equipment

Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning		Automatic Headlights
Bluetooth Connection	Brake Assist System		Car Tire Size - LF tire size P195/65HR15
Car Tire Size - RR tire size P195/65HR15	Car Tire Size - RF tire size P195/65HR15		Car Tire Size - LR tire size P195/65HR15
Child Safety Locks	Cruise Control		Cylinders - 4
Daytime Running Lights	Driver Air Bag		Dual Air Conditioning
Empty Weight - 2996 lb	Engine Immobilizer		Floor Mats
Front Wheel Drive	Front Wheel Drive		HD Radio
Independent Climate Control	Intermittent Wipers		Keyless Entry
Keyless Start	LF Tires - 7/32 inch		LR Tires - 8/32 inch
MP3 Radio	Master Key - 1key(s)		Motor Fuel Type - Other
Pass-Through Rear Seat	Pass. Air Bag		Power Brakes
Power Lock	Power Mirrors		Power Steering
Power Windows	RF Tires - 7/32 inch		RR Tires - 8/32 inch
Rear Defrost	Rear Spoiler		Reverse Camera
Seat Trim - Cloth	Security System		Side Airbags - Front
Steering Wheel Audio Control	Stereo - AM/FM Radio		Tilt Steering Wheel
Tire Pressure Monitor System	Traction Control		Transmission - Automatic Transmission
Trip Computer	Wheels Front Left - Steel		Wheels Front Right - Steel
Wheels Rear Left - Steel	XM Radio		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Chipped	Touch Up	2
	Left Rear Door	Multiple Dents/Paint Damage	Repair	2
	Left Rear Wheel Cover	Chipped	Repair	4
	Right Qtr Panel	Multiple Dents/No Paint Damage	PDR	2
	Right Qtr Panel	Multiple Scratches Heavy	Touch Up	2
	Right Rocker Panel Molding	Heavy Scratch	Repair	3 To 4 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Roof	Chipped	Repair	7
	Rear Bumper	Multiple Scratches Heavy	Repair	7
	Roof	Chipped	Repair	6
	Roof	Corrosion	Repair	1 To 2 Inches
	Right Front Door	Chipped	Touch Up	4
	Right Front Fender	Dent(S) W/ Paint Dmg	Repair	1/2 To 1 Inch
	Right Rear Door	Multiple Scratches Heavy	Touch Up	3
	Right Rear Wheel Cover	Broken	Replace	Replacement Required
[no photo]	Right Front Wheel Cover	Cracked	Replace	Replacement Required
	Front Bumper Cen. Molding	Peeling	Repair	> 12 Inches
	Front Bumper	Broken	Replace	Replacement Required
	Hood	Chipped	Touch Up	4
	Left Qtr Panel	Multiple Dents/Paint Damage	Repair	4

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Roof	Multiple Dents/No Paint Damage	PDR	2
	Left Roof	Multiple Scratches Heavy	Touch Up	2
	Lift Gate	Multiple Scratches Light	Report	3
	Lf Door Handle Cap	Missing	Replace	Replacement Required
	Left Front Door	Multiple Scratches Light	Report	5
	Left Front Door	Heavy Scratch	Touch Up	< 1/8 Inch
	Left Front Fender	Dent(S) W/No Paint Dmg	PDR	1/8 To 1/2 Inch
	Left Front Fender	Scuffed	Report	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.