



Approved CR

IAA Fort Wayne
4300 Oxford St.
Branch No 547
Fort Wayne, IN 46809
(260) 261-0126/(260) 261-0127
WHOLESALE ASSESSMENT ONLY

Make/Model: **2024
HYUNDAI
ELANTRA
HYBRID**

Bodystyle/Series: **4 Door Sedan
BLUE**

Color: **Gray**

Mileage: **38,322
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHLM4DJXRU113600**

Work Order/
Stock Number: **46361642**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G13B0054**

Vehicle Grade : **Grade 0.8**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Coach	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	-	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Drum

Equipment

Additional Equipment:

Car Tire Size - LF 205 / 55 R 16

Car Tire Size - LR 205 / 55 R 16

Car Tire Size - RR 205 / 55 R 16

Car Tire Size - RF 205 / 55 R 16

LF Tires - 5/32 inch

LR Tires - 5/32 inch

RF Tires - 5/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - KUMHO

Tire Brand - Front Right - KUMHO

Tire Brand - Rear Left - KUMHO

Tire Brand - Rear Right - KUMHO

Tire Model - RR - Solus TA31

Tire Model - RF - Solus TA31

Tire Model - LR - Solus TA31

Tire Model - LF - Solus TA31

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Right A Pillar	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Front Bumper	Scraped	-	> 12 Inches
	Rr Seat Air Bag	Deployed	-	Replacement Required
	Rf Seat Air Bag	Deployed	-	Replacement Required
	Right Side Curtain Air Bag	Deployed	-	Replacement Required
	Deck Lid	Heavy Scratch	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches
	Right Rear Door	Multiple Dents/Paint Damage	-	4
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Right Rocker Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Front Door	Severe Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.