Approved
CR

Dealers Auto Auction of Mobile
3030 McVay Drive North
Mobile, AL 36606
2513387653
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Sedan BLUE 4D HATCHBACK**
Color:	**WHITE**
Mileage:	**93,493 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**KMHC65LC4LU219535**
Work Order/ Stock Number:	**000594277**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**133164X**
Vehicle Grade :	**Grade 4.0**
AutoGrade :	**4.4 - Clean**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

ABS Brakes	Air Conditioning	Automatic Headlights
Bluetooth Connection	Brake Assist System	Car Tire Size - Hood
Car Tire Size - RR tire size P195/65HR15	Car Tire Size - LF tire size P195/65HR15	Car Tire Size - RF tire size P195/65HR15
Car Tire Size - LR tire size P195/65HR15	Child Safety Locks	Collision Avoidance
Cruise Control	Cylinders - 4	Daytime Running Lights
Driver Air Bag	Empty Weight - 2996 lb	Engine Immobilizer
Floor Mats	Front Wheel Drive	Front Wheel Drive
Independent Climate Control	Intermittent Wipers	Keyless Entry
Keyless Start	LF Tires - 9/32 inch	LR Tires - 8/32 inch
Lane Departure System	MP3 Radio	Master Key - 1key(s)
Motor Fuel Type - Other	Pass-Through Rear Seat	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	RF Tires - 9/32 inch
RR Tires - 8/32 inch	Rear Defrost	Rear Spoiler
Reverse Camera	Seat Trim - Cloth	Security System
Side Airbags - Front	Steering Wheel Audio Control	Stereo - AM/FM Radio
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - L qtr panel
Tire Brand - Front Left - LF tire mfg Goodyear	Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Cooper
Tire Brand - Rear Right - RR tire mfg Cooper	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown
	Left Front Fender	Photo Only	Estimate Only	Unknown
	Right Front Fender	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	Repair	4
	Left Rocker Panel	Multiple Scratches Heavy	Repair	6
	Left Front Door	Chipped	Repair	3
	Windshield	Chipped	Report	< 1/8 Inch
[no photo]	Rear Bumper	Multiple Scratches Heavy	Repair	8
[no photo]	Front Bumper	Chipped	Repair	4
[no photo]	Left Qtr Panel	Chipped	Repair	3
[no photo]	Left Rear Door	Chipped	Repair	3
[no photo]	Left Rear Wheel Cover	Heavy Scratch	Repair	2 To 3 Inches
[no photo]	Right Front Door	Chipped	Repair	3
[no photo]	Right Front Fender	Chipped	Repair	3
[no photo]	Right Rear Door	Chipped	Repair	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.