Approved CR

IAA Newburgh
39 Stone Castle Road
Branch No 635
Rock Tavern, NY 12575
(845) 567-6360/(845) 567-6366
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2022 NISSAN SENTRA**
Bodystyle/Series:	**4 Door Sedan S XTRONIC CVT**
Color:	**Black**
Mileage:	**83,371 (Verified)**
Turn-in Mileage:	-
VIN:	**3N1AB8BV2NY234372**
Work Order/ Stock Number:	**46495762**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G132195Y**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment


Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**5th**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 205 / 60 R 16	Car Tire Size - RF 205 / 60 R 16	Car Tire Size - LF 205 / 60 R 16
Car Tire Size - LR 205 / 60 R 16	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 7/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - NIKA
Tire Brand - Front Right - NIKA	Tire Brand - Rear Left - NIKA	Tire Brand - Rear Right - NIKA
Tire Model - LF - Avatar	Tire Model - LR - Avatar	Tire Model - RF - Avatar
Tire Model - RR - Avatar		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Multiple Scratches Heavy	-	2
	Right Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Right Rear Door	Chipped	-	2
	Front Bumper	Chipped	-	4
	Right Front Wheel Cover	Curb Rash	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Multiple Scratches Heavy	-	4
	Left Rear Wheel Cover	Curb Rash	-	5 To 6 Inches
	Roof	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.