



Approved CR

America's Auto Auction - Pensacola, Inc
 6615 Mobile Highway
 Pensacola, FL 32526-1264
 850-972-8601/(850) 944-8482
 Della.Smith@AmericasAutoAuction.com
 WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
F-150**
 Bodystyle/Series: **4 Door Vehicle
XL
SUPERCREW
4WD**
 Color: **BLACK**
 Mileage: **96,329
(Verified, 6
digits)**
 Turn-in Mileage: **-**
 VIN: **1FTEW1EB0LKD26474**
 Work Order/
 Stock Number: **000355593**
 Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
 Client Stock #: **G626784W**
 Vehicle Grade : **Grade 3.5**
 Remarks: **-**
 Announcements: **-**
 Certification : **Not Certified**
 Req. Prev. Repair **-**
 Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

4 Wheel Drive	4 Wheel Drive	4th Passenger Door
ABS Brakes	Air Conditioning	Automatic Headlights
Auxiliary Pwr Outlet	Bench Seating	Bluetooth Connection
Brake Assist System	Car Tire Size - RF tire size P265/70SR17	Car Tire Size - LR tire size P265/70SR17
Car Tire Size - LF tire size P265/70SR17	Car Tire Size - RR tire size P265/70SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Empty Weight - 4770 lb	Engine Immobilizer
Independent Climate Control	Intermittent Wipers	Keyless Entry
LF Tires - 7/32 inch	LR Tires - 7/32 inch	Master Key - 1key(s)
Motor Fuel Type - Gas	Pass. Air Bag	Power Brakes
Power Folding Mirrors	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Rear Defrost
Reverse Camera	Running Board	Seat Trim - Cloth
Security System	Side Airbags - Front	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Goodyear
Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear	Tire Brand - Rear Right - RR tire mfg Goodyear
Tire Pressure Monitor System	Tow Hitch	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Seat	Stained	Report	Permanent
	Right Rear Door	Multiple Scratches Light	Report	3
	Right Rear Seat	Stained	Report	Permanent
	Seat Center Rear	Stained	Report	Permanent
	Tailgate	Multiple Scratches Light	Report	6
[no photo]	Horn	Inoperable	Report	Repair Required
[no photo]	Oil	Low Fluid	Report	Unacceptable
[no photo]	4 Wheel Drive	Aftermarket	Report	Acceptable
	Grille	Multiple Scratches Light	Report	3
	Front Bumper	Multiple Scratches Light	Report	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Headlining	Aftermarket	Report	Acceptable
	Hood	Multiple Scratches Light	Report	6
	Left Bed Side	Multiple Scratches Light	Report	6
	Corner Panel	Multiple Scratches Light	Report	5
	Left Front Door	Multiple Scratches Light	Report	3
	Left Front Fender	Multiple Scratches Light	Report	3
	Left Front Seat	Stained	Report	Permanent
	Left Front Seat	Worn	Report	Acceptable
	Left Rear Door	Multiple Scratches Light	Report	5
	Left Rear Seat	Stained	Report	Permanent
	Pickup Bed	Multiple Scratches Heavy	Report	10 Or More
	Right Bed Side	Multiple Scratches Light	Report	5
	Rear Bumper	Multiple Dents/No Paint Damage	Report	6

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Corner Panel	Multiple Scratches Light	Report	4
	Roof	Multiple Scratches Light	Report	5
	Right Front Door	Multiple Scratches Light	Report	9
	Right Front Fender	Multiple Scratches Light	Report	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.