



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
EXPEDITION**
Bodystyle/Series: **4 Door Sport
Utility
Vehicle XL
4D SUV 4WD**
Color: **WHITE**
Mileage: **63,734
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **1FMJU1GT8GEF01435**
Work Order/
Stock Number: **000355592**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G62A0114**
Vehicle Grade : **Grade 4.2**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair
Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas Turbo	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /TAN	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	Power	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

2nd Row Bucket Seats	4 Wheel Drive	4 Wheel Drive
4th Passenger Door	ABS Brakes	Air Conditioning
Automatic Headlights	Auxiliary Pwr Outlet	Brake Assist System
CD Player	Car Tire Size - RR tire size P265/70SR17	Car Tire Size - LR tire size P265/70SR17
Car Tire Size - LF tire size P265/70SR17	Car Tire Size - RF tire size P265/70SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Electrochromic Rearview Mirror	Empty Weight - 5789 lb
Engine Immobilizer	Floor Mats	Fog Lamps
Heated Mirrors	Independent Climate Control	Intermittent Wipers
Keyless Entry	LF Tires - 8/32 inch	LR Tires - 9/32 inch
Leather Steering Wheel	Luggage Rack	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Driver Seat	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 8/32 inch	RR Tires - 9/32 inch
Rear AC	Rear Defrost	Rear Seat Audio Controls
Reverse Camera	Running Board	Seat Trim - Cloth
Security System	Side Airbags - Front	Tilt Steering Wheel
Tilt Wheel	Tire Brand - Front Left - LF tire mfg Pathfinder	Tire Brand - Front Right - RF tire mfg Pathfinder
Tire Brand - Rear Left - LR tire mfg Pathfinder	Tire Brand - Rear Right - RR tire mfg Pathfinder	Tire Pressure Monitor System
Tow Hitch	Traction Control	Transmission - Automatic Transmission w/ Overdrive
Turbocharged	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown




Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Chipped	Report	3
	Left Front Door	Multiple Dents/Paint Damage	Report	3
	Right Front Door	Multiple Scratches Light	Report	6
	Right Front Fender	Multiple Scratches Light	Report	4
[no photo]	Oil	Low Fluid	Report	Unacceptable
	Roof	Chipped	Report	5
	Left Qtr Panel	Multiple Scratches Light	Report	6
	Hood	Multiple Scratches Light	Report	6
	Headlining	Stained	Report	Permanent

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Chipped	Report	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.