



Approved CR

IAA High Desert
11385 G Avenue
Branch No 133
Hesperia, CA 92345
(760)949-8404/(760)949-0400
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
CHEVROLET
EXPRESS
PASSENGER**

Bodystyle/Series: **Van RWD
3500
EXTENDED**

Color: **White**

Mileage: **74,639
(Verified)**

Turn-in Mileage: **-**

VIN: **1GAZGNFGXL1116138**

Work Order/
Stock Number: **46272258**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G434281W**

Vehicle Grade : **Grade 4.2**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LR 245 / 75 R 16

Car Tire Size - RR 245 / 75 R 16

Car Tire Size - RF 245 / 75 R 16

Car Tire Size - LF 245 / 75 R 16

LF Tires - 11/32 inch

LR Tires - 10/32 inch

RF Tires - 11/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - FALKEN

Tire Brand - Front Right - fal

Tire Brand - Rear Left - fal

Tire Brand - Rear Right - fal

Tire Model - LF - Wildpeak H/T

Tire Model - LR - Wildpeak H/T


Tire Model - RF - Wildpeak H/T

Tire Model - RR - Wildpeak H/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Grille Molding	Chipped	-	3
	Right Rocker Panel	Dent(S) W/No Paint Dmg	-	3 To 4 Inches
	Windshield	Chipped	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.