Approved CR

IAA Oklahoma City
7300 N 1-35 Service RD
Branch No 421
Oklahoma City, OK 73121
(405) 475-0230/(405) 680-9204
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 FORD FOCUS**
Bodystyle/Series:	**4 Door Sedan SE**
Color:	**Silver**
Mileage:	**66,868 (Verified)**
Turn-in Mileage:	-
VIN:	**1FADP3F22GL365575**
Work Order/ Stock Number:	**43583190**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**3691G691V**
Vehicle Grade :	**Grade 0.0**
Remarks:	-
Announcements:	• salvage
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	-	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment


Additional Equipment:

Car Tire Size - LF 215 / 55 R 16	Car Tire Size - LR 215 / 55 R 16	Car Tire Size - RR 215 / 55 R 16
Car Tire Size - RF 215 / 55 R 16	LF Tires - 7/32 inch	LR Tires - 9/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - SUREDRIVE
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - RR - Ziex ZE960 A/S	Tire Model - RF - Ziex ZE960 A/S	Tire Model - LR - Ziex ZE960 A/S
Tire Model - LF - All-Season		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Apron	Kinked	-	> 12 Inches
	Left A Pillar	Kinked	-	> 12 Inches
	Left Front Rail	Kinked	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Core Support	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Front Fender	Severe Damage	-	Replacement Required
	Left Front Mirror Housing	Broken	-	Replacement Required
	Right Front Door	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Grille	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Missing	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required
	Lf Axle Assembly	Broken	-	Replacement Required
	Front Bumper Reinforcement	Broken	-	Replacement Required
	Electrical Box (Fuse Panel)	Broken	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Drip Rail	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Left Front Wheel	Curb Rash	-	6 To 7 Inches
	Left Knee Airbag	Deployed	-	Replacement Required
	Airbag - Front Left	Deployed	-	Replacement Required
	Windshield	Broken	-	Replacement Required
	Air Filter Housing	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	2 To 3 Inches
	Front Bumper	Severe Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.