



Approved CR

IAA Dothan
15994 Us Highway 431 N
Branch No 731
Headland, AL 36345
(334) 693-4910/(334) 693-4920
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 FORD
F-150
LIGHTNING**

Bodystyle/Series: **Crew Cab
PRO**

Color: **Blue**

Mileage: **3,937
(Verified)**

Turn-in Mileage: **-**

VIN: **1FTVW1EL5PWG11341**

Work Order/
Stock Number: **46415017**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G625148Z**

Vehicle Grade : **Grade 1.4**

Remarks: **-**

Announcements: **• Salvage**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	-	Cruise Control:	Yes
Engine Size:	-	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 65 R 18

Car Tire Size - LR 275 / 65 R 18

Car Tire Size - RR 275 / 65 R 18

Car Tire Size - RF 275 / 65 R 18

LF Tires - 6/32 inch

LR Tires - 9/32 inch

RF Tires - 8/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - MICHELIN

Tire Brand - Front Right - MICHELIN

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - RR - Primacy XC

Tire Model - RF - Primacy XC

Tire Model - LR - Primacy XC

Tire Model - LF - Primacy XC

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	L -B- Pillar	Kinked	-	4 To 5 Inches
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Severe Damage	-	Replacement Required
	Left Front Door	Severe Damage	-	Replacement Required
	L Cab Corner Panel	Dent(S) W/ Paint Dmg	-	8 To 9 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Bed Side	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Right Bed Side	Light Scratch	-	> 12 Inches
	Right Head Lamp	Broken	-	Replacement Required
	Inside Bed	Heavy Scratch	-	> 12 Inches
	Left Tail Light	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.