Approved CR

Dealers Auto Auction of Cincinnati, LLC
120 City Centre Drive
Cincinnati, OH 45216
513-679-7910/513-679-7913
aschoenling@dealersauto.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2021 FORD ESCAPE**
Bodystyle/Series:	**Sport Utility Vehicle S**
Color:	**BLUE**
Mileage:	**80,069 (Digital)**
Turn-in Mileage:	-
VIN:	**1FMCU0F68MUA82504**
Work Order/ Stock Number:	**0052528**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**102619I2A82504**
Vehicle Grade :	**Grade 3.5**
Remarks:	-
Announcements:	• As Is • AS IS
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**3-Cylinder Gas Turbo**	Cruise Control:	**Yes**
Engine Size:	**1.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	- **/GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4th Passenger Door	Automatic Headlights	Auxiliary Pwr Outlet
Backup camera and monitor	Blind Spot Monitor	Bluetooth Connection
Brake Assist System	Car LF Tires - 6/32 inch	Car LR Tires - 7/32 inch
Car RF Tires - 7/32 inch	Car RR Tires - 5/32 inch	Car Tire Size - LF: P225/65HR17 LR: P225/65HR17 RF: P225/65HR17 RR: P225/65HR17 SP: SPACE SAVER
Child Safety Locks	Cross - Traffic Alert	Cylinders - 3
Daytime Running Lights	Driver Restriction Features	Driver Vanity Mirror
Electronic Stability Control	Engine Immobilizer	Floor Mats
Forward Collision Alert System	Front Head Air Bag	Ignition Key - 2key(s)
Independent Climate Control	Intermittent Wipers	Knee Air Bag
LF Tires - 6/32 inch	LR Tires - 7/32 inch	Lane Departure System
Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch, Automatic Highbeams, Driver Monitoring, Rear Collisi	Pass. Air Bag	Passenger Air Bag Sensor
Passenger Vanity Mirror	Power Mirrors	Privacy Glass
RF Tires - 7/32 inch	RR Tires - 5/32 inch	Rear Bench Seat
Rear Head Air Bag	Rear Spoiler	Side Airbags - Front
Smart Device Integration	Spare Tire - Space Saver	Spare Tire Brand - MAXXIS
Spare Tire Tread - 4/32 inch	Spare Wheel - Steel	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - KELLY
Tire Brand - Front Right - KELLY	Tire Brand - Rear Left - KELLY	Tire Brand - Rear Right - KELLY
Tire LF - 6/32 inch	Tire Pressure Monitor System	Tire RF - 7/32 inch
Tire Size - LF: P225/65HR17 LR: P225/65HR17 RF: P225/65HR17 RR: P225/65HR17 SP: SPACE SAVER	Tire Size - LF: P225/65HR17 LR: P225/65HR17 RF: P225/65HR17 RR: P225/65HR17 SP: SPACE SAVER	Transmission - Automatic Transmission
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel
WiFi Hotspot		

Non Chargeable Damages

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	Refinish	10 Or More
	Left Front Door	Chipped	Refinish	10 Or More
	Left Rear Door	Chipped	Touch Up	3
	Left Qtr Panel	Light Scratch	Wet Sand	1 To 2 Inches
	Rear Bumper/Cover	Light Scratch	Wet Sand	1 To 2 Inches
	Right Front Door	Chipped	Touch Up	1
[no photo]	Engine	Tap	Repair	Repair Required
[no photo]	Fuel Injection System	Worn	Report	Replacement Required
	Left Front Seat	Stained	Detail	Permanent
	Warning Light - Engine	On	Mechanical Check	Unacceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.