



Approved CR

Mid Kansas Auto Auction Wichita
4716 S. Santa Fe
Wichita , KS 67216
316-500-7700/316-500-7701
codyd@mksaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
TRANSIT
CONNECT**
4 Door Vehicle

Bodystyle/Series: **XLT
PASSENGER
WAGON
WAGON**

Color: **RED**

Mileage: **71,563
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **NM0GE9F27L1436465**

Work Order/
Stock Number: **000116313**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **-**

Vehicle Grade : **Grade 4.2**

AutoGrade : **4.2 - Clean**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	Power	Drive Type:	Front Wheel Drive

Equipment

Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
3rd Row Seat	4th Passenger Door	ABS Brakes	
Air Conditioning	Automatic Headlights	Auxiliary Pwr Outlet	
Blind Spot Monitor	Bluetooth Connection	Brake Assist System	
Car Tire Size - LR tire size P215/55HR16	Car Tire Size - RF tire size P215/55HR16	Car Tire Size - RR tire size P215/55HR16	
Car Tire Size - LF tire size P215/55HR16	Child Safety Locks	Cruise Control	
Cylinders - 4	Daytime Running Lights	Driver Air Bag	
Dual Air Conditioning	Empty Weight - 4028 lb	Engine Immobilizer	
Floor Mats	Fog Lamps	Front Wheel Drive	
Front Wheel Drive	Heated Mirrors	Independent Climate Control	
Intermittent Wipers	Keyless Entry	LF Tires - 10/32 inch	
LR Tires - 9/32 inch	Lane Departure System	Leather Steering Wheel	
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag	
Power Brakes	Power Driver Seat	Power Folding Mirrors	
Power Lock	Power Mirrors	Power Steering	
Power Windows	Privacy Glass	RF Tires - 10/32 inch	
RR Tires - 10/32 inch	Rain Sensor	Rear AC	
Rear Defrost	Rear Parking Aid	Reverse Camera	
Seat Trim - Cloth	Side Airbags - Front	Steering Wheel Audio Control	
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Goodyear	
Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear	Tire Brand - Rear Right - RR tire mfg Goodyear	
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission w/ Overdrive	
Trip Computer	Wheels Front Left - Steel	Wheels Front Right - Steel	
Wheels Rear Left - Steel	Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lift Gate	Chipped	Touch Up	3
	Left Front Door	Chipped	Touch Up	3
	Left Front Door	Multiple Dents/No Paint Damage	PDR	Pdr-3 Dents
	Left Front Fender	Chipped	Touch Up	4
	Left Rear Door	Chipped	Touch Up	3
	Left Rear Door	Multiple Dents/No Paint Damage	PDR	Pdr-4 Dents
	Rear Bumper/Cover	Multiple Scratches Heavy	Touch Up	6
	Roof	Multiple Dents/No Paint Damage	PDR	Pdr-6 Dents
	Right Front Door	Chipped	Touch Up	4
	Right Front Door	Dent(S) W/ Paint Dmg	Repair	1/8 To 1/2 Inch
	Right Front Fender	Chipped	Touch Up	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Chipped	Touch Up	4
	Hood	Chipped	Touch Up	5
	Left Qtr Panel	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Rocker Panel	Multiple Scratches Heavy	Touch Up	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.