Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

| | |
|---|---|
| Make/Model: | **2018 CHEVROLET EQUINOX** |
| Bodystyle/Series: | **Sport Utility Vehicle LS** |
| Color: | **White** |
| Mileage: | **21,115 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **2GNAXREV8J6314567** |
| Work Order/ Stock Number: | **46377845** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G610978V** |
| Vehicle Grade : | **Grade 3.8** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |




Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **4-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **1.5 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /GRAY** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Memory** | Drive Type: | **All Wheel Drive** |
| Seat Count: | - | Brakes: | **Hydraulic Brakes** |

## Equipment


Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - RR 225 / 65 R 17 | Car Tire Size - RF 225 / 65 R 17 | Car Tire Size - LF 225 / 65 R 17 |
| Car Tire Size - LR 225 / 65 R 17 | LF Tires - 5/32 inch | LR Tires - 3/32 inch |
| RF Tires - 6/32 inch | RR Tires - 3/32 inch | Tire Brand - Front Left - BRIDGESTONE |
| Tire Brand - Front Right - BRIDGESTONE | Tire Brand - Rear Left - BRIDGESTONE | Tire Brand - Rear Right - BRIDGESTONE |
| Tire Model - LF - Ecopia H/L 422 Plus | Tire Model - LR - Ecopia H/L 422 Plus | Tire Model - RF - Ecopia H/L 422 Plus |
| Tire Model - RR - Ecopia H/L 422 Plus | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Keys | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Bumper | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Engine | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Front Seat Cushion | Stained | - | Permanent |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Tire | Worn | - | Replacement Required |
|  | Left Rear Tire | Worn | - | Replacement Required |
|  | Right Head Lamp | Faded | - | Repair Required |
|  | Left Head Lamp | Faded | - | Repair Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.