



Approved CR

IAA Atlanta West
1871 Rome Hwy
Branch No 793
Rockmart, GA 30153
(470) 598-3740
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
F-150**
Bodystyle/Series: **Crew Cab XL**
Color: **Silver**
Mileage: **71,263
(Verified)**
Turn-in Mileage: **-**
VIN: **1FTEW1E84HKD63720**
Work Order/
Stock Number: **46356687**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G622309U**
Vehicle Grade : **Grade 2.7**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment




Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 6/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Wrangler Workhorse At	Tire Model - RF - Wrangler Workhorse At	Tire Model - LR - Wrangler Workhorse At
Tire Model - LF - Wrangler Workhorse At		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Traction Control	On	-	Unacceptable
	Warning Light - Abs	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	4
	Left Rear Wheel	Peeling	-	9 To 10 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Steering Wheel	Worn	-	Replacement Required
	Left Rear Door	Multiple Scratches Light	-	4
	Cab - Left	Multiple Scratches Light	-	3
	Left Front Fender	Multiple Scratches Light	-	4
	Right Front Wheel	Peeling	-	9 To 10 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Chipped	-	2
	Right Rear Wheel	Peeling	-	5 To 6 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.