Approved CR

IAA El Paso
14751 Marina Ave
Branch No 420
El Paso, TX 79938
(915)852-2489/(915)852-2235
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 FORD F-250**
Bodystyle/Series:	**Extended Cab XL**
Color:	**White**
Mileage:	**47,671 (Verified)**
Turn-in Mileage:	-
VIN:	**1FT7X2B63GEC75852**
Work Order/ Stock Number:	**46415887**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G631876S**
Vehicle Grade :	**Grade 3.9**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Leather/Cloth Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Hydraulic Brakes**

Equipment


Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 11/32 inch	LR Tires - 11/32 inch
RF Tires - 11/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - IRONMAN
Tire Brand - Front Right - IRONMAN	Tire Brand - Rear Left - IRONMAN	Tire Brand - Rear Right - IRONMAN
Tire Model - RR - All Country AT2	Tire Model - RF - All Country AT2	Tire Model - LR - All Country AT2
Tire Model - LF - All Country AT2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Left Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.