Approved CR

IAA Tucson
4650 E Irvington Rd
Branch No 424
Tucson, AZ 85714
(520) 319-9393 /(520) 519-9491
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 FORD F-350**
Bodystyle/Series:	**Crew Cab XL**
Color:	**Gray**
Mileage:	**25,357 (Verified)**
Turn-in Mileage:	-
VIN:	**1FT8W3D67GED16350**
Work Order/ Stock Number:	**46462564**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G630316V**
Vehicle Grade :	**Grade 2.4**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.2 L**	Pwr Steering:	**No**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17	Car Tire Size - RF 245 / 75 R 17	Car Tire Size - LF 245 / 75 R 17
Car Tire Size - LR 245 / 75 R 17	LF Tires - 7/32 inch	LR Tires - 6/32 inch
RF Tires - 7/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - LF - Dynapro HT RH12 (LT-Metric)	Tire Model - LR - Dynapro HT RH12 (LT-Metric)	Tire Model - RF - Dynapro HT RH12 (LT-Metric)
Tire Model - RR - Dynapro HT RH12 (LT-Metric)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Multiple Scratches Heavy	-	4
	Right Front Wheel	Corrosion	-	1/2 To 1 Inch
	Right Qtr Flare	Multiple Scratches Light	-	3
	Right Bed Side	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Rear Wheel	Curb Rash	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	4 To 5 Inches
	Tailgate	Multiple Dents/Paint Damage	-	5
	Tailgate Protective Cap	Missing	-	Replacement Required
	Left Qtr Flare	Multiple Scratches Heavy	-	5
	Left Bed Side	Multiple Scratches Heavy	-	3
	Left Rear Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Roof	Multiple Scratches Light	-	3
	Left Rear Seat Cushion	Torn	-	7 To 8 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Right Bed Side	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.