



Approved CR

IAA Kansas City
2663 S 88th Street
Branch No 527
Kansas City, KS 66111
(913) 422-9303/(913) 422-7421
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
TRANSIT
CONNECT**

Bodystyle/Series: **4 Door
Wagon XL**

Color: **Gray**

Mileage: **13,946
(Verified)**

Turn-in Mileage: **-**

VIN: **NM0GE9E79G1278617**

Work Order/
Stock Number: **46378884**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G412250S**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment



Additional Equipment:

Car Tire Size - RR 215 / 55 R 16	Car Tire Size - RF 215 / 55 R 16	Car Tire Size - LF 215 / 55 R 16
Car Tire Size - LR 215 / 55 R 16	LF Tires - 6/32 inch	LR Tires - 8/32 inch
RF Tires - 6/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - CONTINENTAL
Tire Brand - Front Right - CONTINENTAL	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - CONTINENTAL
Tire Model - LF - Contiprocontact	Tire Model - LR - Contiprocontact	Tire Model - RF - Contiprocontact
Tire Model - RR - Contiprocontact		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lift Gate	Chipped	-	10 Or More
	Left Front Door	Chipped	-	5
	Left Front Fender	Heavy Scratch	-	< 1/8 Inch
	Hood	Chipped	-	2
	Front Bumper Cover Upper	Heavy Scratch	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Misaligned	-	Repair Required
	Right Front Door	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.