



Approved CR

IAA Paducah
1701 Land Road
Branch No 659
Paducah, KY 42003
(270) 443-8565/(270) 0443-8549
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 IC CORPORATION 3000**
Bodystyle/Series: **- RE**
Color: **White**
Mileage: **62,767 (Verified)**
Turn-in Mileage: **-**
VIN: **4DRBXAAN8FB682798**
Work Order/
Stock Number: **46396881**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G320377Z**
Vehicle Grade : **Grade 3.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	No
Engine Size:	7.6 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	-/-	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-
Additional Equipment:	-		

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Vehicle	De-Identify	-	Removal Required
	Right Rear Tire	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Worn	-	Replacement Required
	Left Rear Tire	Worn	-	Replacement Required
	Rear Ls Panel Extension	Dent(S) W/ Paint Dmg	-	4 To 5 Inches
	Right Qtr Panel Extension	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Right Side Panel	Peeling	-	3 To 4 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Tire	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.