



Approved
CR

IAA Burlington
304 Colchester Road
Branch No 645
Essex, VT 05451
(802) 872-7838/(802) 878-8353
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
TRANSIT
CONNECT**

Bodystyle/Series: **Wagon XL**

Color: **Black**

Mileage: **69,903 (Verified)**

Turn-in Mileage: **-**

VIN: **NM0GE9E24K1426492**

Work Order/
Stock Number: **46368822**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G411149W**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements:

**• ANNOUNCEMENTS:
Rust**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	4th	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 55 R 16

Car Tire Size - RF 215 / 55 R 16

Car Tire Size - LF 215 / 55 R 16

Car Tire Size - LR 215 / 55 R 16

LF Tires - 8/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - KELLY

Tire Brand - Front Right - KELLY

Tire Brand - Rear Left - KELLY

Tire Brand - Rear Right - KELLY

Tire Model - LF - Edge Touring A/S

Tire Model - LR - Edge Touring A/S

Tire Model - RF - Edge Touring A/S

Tire Model - RR - Edge Touring A/S

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Lf Strut	Rust	-	Severe Damage
	Right Front Door Panel	Multiple Scratches Light	-	3
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Heavy Scratch	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Chipped	-	2
	Right Front Wheel Cover	Peeling	-	> 12 Inches
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Rear Wheel Cover	Peeling	-	> 12 Inches
	Lift Gate	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Qtr Panel	Multiple Scratches Light	-	7

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel Cover	Peeling	-	> 12 Inches
	Left Front Wheel Cover	Peeling	-	> 12 Inches
	Roof	Light Scratch	-	1/2 To 1 Inch
	Left Qtr Panel	Scuffed	-	4 To 5 Inches
	Left Rear Door	Light Scratch	-	9 To 10 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.