



Approved CR

Dealers Auto Auction of Little Rock
4600 S University Ave
Little Rock , AR 72204
501-904-9988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD F-150**
4 Door Vehicle
Bodystyle/Series: **XL**
SUPERCREW
4WD
Color: **WHITE**
Mileage: **67,039**
(Verified, 6 digits)
Turn-in Mileage: **-**
VIN: **1FTEW1EB9JKE38297**
Work Order/
Stock Number: **000074300**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G623337V**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

4 Wheel Drive	4 Wheel Drive	4th Passenger Door
ABS Brakes	Air Conditioning	Automatic Headlights
Auxiliary Pwr Outlet	Bench Seating	Bluetooth Connection
Brake Assist System	Car Tire Size - LR tire size P265/70SR17	Car Tire Size - RF tire size P265/70SR17
Car Tire Size - RR tire size P265/70SR17	Car Tire Size - LF tire size P265/70SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Empty Weight - 4769 lb	Engine Immobilizer
Independent Climate Control	Intermittent Wipers	Keyless Entry
LF Tires - 10/32 inch	LR Tires - 10/32 inch	Master Key - 2key(s)
Motor Fuel Type - Gas	Pass. Air Bag	Power Brakes
Power Folding Mirrors	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Rear Defrost
Reverse Camera	Seat Trim - Cloth	Security System
Side Airbags - Front	Steering Wheel Audio Control	Telematics
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - LF tire mfg Cooper
Tire Brand - Front Left - Hood	Tire Brand - Front Right - RF tire mfg Cooper	Tire Brand - Rear Left - LR tire mfg Cooper
Tire Brand - Rear Right - RR tire mfg Cooper	Tire Pressure Monitor System	Tow Hitch
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Trip Computer
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Scratches Heavy	Touch Up	3
	Right Front Fender	Dent(S) W/ Paint Dmg	Report	< 1/8 Inch
	Right Front Door	Dent(S) W/ Paint Dmg	Report	1 To 2 Inches
	Right Front Door	Dent(S) W/No Paint Dmg	Report	1/8 To 1/2 Inch
	Right Bed Side	Scuffed	Wet Sand	2 To 3 Inches
	Grille	Bug Damage	Detail	Repair Required
	Front Bumper/Cover	Bug Damage	Detail	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.