



Approved CR

IAA Raleigh
60 Sadisco Road
Branch No 747
Clayton, NC 27520
(919) 553-6148/(919) 553-2857
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT-350**
Bodystyle/Series: **Wagon XL**
Color: **Black**
Mileage: **81,076
(Verified)**
Turn-in Mileage: **-**
VIN: **1FBZX2ZM2JKB31266**
Work Order/
Stock Number: **46399821**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G432348V**
Vehicle Grade : **Grade 3.7**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc


Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 16	Car Tire Size - RR 235 / 65 R 16	Car Tire Size - LR 235 / 65 R 16
Car Tire Size - RF 235 / 65 R 16	LF Tires - 5/32 inch	LR Tires - 4/32 inch
RF Tires - 4/32 inch	RR Tires - 2/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - Transforce CV	Tire Model - RF - Transforce CV	Tire Model - LR - Transforce CV
Tire Model - LF - Transforce CV		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	3 To 4 Inches
	Right Rear Tire	Worn	-	Replacement Required
	Right Rear Cargo Door	Chipped	-	2
	Left Rear Cargo Door	Chipped	-	2
	Rear Ls Panel	Multiple Dents/No Paint Damage	-	2
	Left Rear Wheel	Curb Rash	-	9 To 10 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Roof	Chipped	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.