



Approved CR

IAA Raleigh
60 Sadisco Road
Branch No 747
Clayton, NC 27520
(919) 553-6148/(919) 553-2857
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 BLUE
BIRD
SCHOOL
BUS /
TRANSIT
BUS**

Bodystyle/Series: - -

Color: **White**

Mileage: **67,201
(Verified)**

Turn-in Mileage: -

VIN: **1BABLCPA5GF320027**

Work Order/
Stock Number: **46399785**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G32A0460**

Vehicle Grade : **Grade 2.1**

Remarks: -

Announcements: -

Certification : -

Req. Prev. Repair -

Order: -



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	No
Engine Size:	6.7 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /-	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-
Additional Equipment:	-		

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	5th Row Left Seat Back	Torn	-	> 12 Inches
	Right Seat Back 4th Row	Torn	-	> 12 Inches
	Left Seat Back 4th Row	Torn	-	> 12 Inches
	Right 3rd Row Seat Cushion	Torn	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left 3rd Row Seat Cushion	Torn	-	> 12 Inches
	Right Rear Seat Cushion	Torn	-	> 12 Inches
	Left Rear Seat Bolster	Torn	-	> 12 Inches
	Exterior Rear Body Panel	Multiple Dents/Paint Damage	-	4
	Rear Metal Bumper Painted	Heavy Scratch	-	1 To 2 Inches
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rocker Panel	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Front Window	Cracked	-	Replacement Required
	Front Roof Panel	Multiple Scratches Heavy	-	3
	5th Row Right Seat Back	Torn	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.