Approved CR

Capital City Auto Auction
600 Winfield Rd
St. Albans, WV 25177
(304) 201-2270/(304)201-2284
brandon@capitalcityaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2022 CHRYSLER VOYAGER**
Bodystyle/Series:	**Van LX WAGON**
Color:	**BLACK**
Mileage:	**100,429 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**2C4RC1CG7NR146583**
Work Order/ Stock Number:	**000667390**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G41 1517Y**
Vehicle Grade :	**Grade 2.5**
AutoGrade :	**2.3 - Below Average**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: YES

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

2nd Row Bucket Seats	3rd Row Seat	4th Passenger Door
ABS Brakes	Air Conditioning	Automatic Headlights
Bluetooth Connection	Brake Assist System	Car Tire Size - LF tire size P235/65HR17
Car Tire Size - LR tire size P235/65HR17	Car Tire Size - RF tire size P235/65HR17	Car Tire Size - RR tire size P235/65HR17
Child Safety Locks	Cruise Control	Cylinders - 6
Daytime Running Lights	Driver Air Bag	Dual Air Conditioning
Empty Weight - 4330 lb	Engine Immobilizer	Floor Mats
Front Wheel Drive	Front Wheel Drive	Heated Front Seat(s)
Heated Mirrors	Heated Steering Wheel	Independent Climate Control
Intermittent Wipers	Keyless Entry	Keyless Start
LF Tires - 5/32 inch	LR Tires - 7/32 inch	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Driver Seat	Power Lift Gate
Power Lock	Power Mirrors	Power Steering
Power Windows	Privacy Glass	RF Tires - 5/32 inch
RR Tires - 7/32 inch	Rear AC	Rear Defrost
Rear Spoiler	Remote Trunk Release	Reverse Camera
Seat Trim - Cloth	Security System	Side Airbags - Front
Steering Wheel Audio Control	Stereo - AM/FM Radio	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Cooper	Tire Brand - Front Right - RF tire mfg Cooper	Tire Brand - Rear Left - LR tire mfg Cooper
Tire Brand - Rear Right - RR tire mfg Cooper	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Aluminium
Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium
XM Radio		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown



Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Sliding Door	Severe Damage	Replace	Replacement Required
	Rear Bumper/Cover	Multiple Scratches Heavy	Repair	10 Or More
	Right Front Door	Severe Damage	Replace	Replacement Required
	Right Front Fender	Severe Damage	Replace	Replacement Required
	Windshield	Cracked	Replace	> 12 Inches
	Front Bumper/Cover	Chipped	Touch Up	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Multiple Scratches Heavy	Repair	10 Or More
	Hood	Chipped	Touch Up	10 Or More
	Left Front Fender	Chipped	Touch Up	6
	Right Qtr Flare Red Lamp	Broken	Replace	Replacement Required
	Right Qtr Panel	Severe Damage	Replace	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.