Approved CR

Dealers Auto Auction of Huntsville
26125 US Highway 72
Athens, AL 35613
256-232-0201
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 FORD EXPEDITION**
Bodystyle/Series:	**4 Door Sport Utility Vehicle XL 4D SUV 4WD**
Color:	**GRAY**
Mileage:	**69,485 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1FMJU1GT5GEF50866**
Work Order/ Stock Number:	**000230798**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G62-2649S**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Gas Turbo**	Cruise Control:	**Yes**
Engine Size:	**3.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM CD**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

2nd Row Bucket Seats	3rd Row Seat	4 Wheel Drive
4 Wheel Drive	4th Passenger Door	ABS Brakes
Air Conditioning	Automatic Headlights	Auxiliary Pwr Outlet
Bluetooth Connection	Brake Assist System	CD Player
Car Tire Size - RR tire size P265/70SR17	Car Tire Size - LR tire size P265/70SR17	Car Tire Size - LF tire size P265/70SR17
Car Tire Size - Hood	Car Tire Size - RF tire size P265/70SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Electrochromic Rearview Mirror	Empty Weight - 5789 lb
Engine Immobilizer	Floor Mats	Fog Lamps
Heated Mirrors	Independent Climate Control	Intermittent Wipers
Keyless Entry	Leather Steering Wheel	Luggage Rack
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Gas
Pass. Air Bag	Power Brakes	Power Driver Seat
Power Lock	Power Mirrors	Power Steering
Power Windows	Privacy Glass	Rear AC
Rear Defrost	Rear Seat Audio Controls	Reverse Camera
Running Board	Seat Trim - Cloth	Security System
Side Airbags - Front	Steering Wheel Audio Control	Telematics
Tilt Steering Wheel	Tire Pressure Monitor System	Tow Hitch
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Turbocharged
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Right Front Fender	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Left Front Fender	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Scraped	Repair	1 To 2 Inches
	Lift Gate	Heavy Scratch	Refinish	3 To 4 Inches
	Left Front Door	Heavy Scratch	Refinish	2 To 3 Inches
	Left Front Fender	Chipped	Repair	1
	Rear Bumper	Enviro Paint Damage	Report	4 To 5 Inches
	Right Front Door	Chipped	Repair	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Chipped	Refinish	3
	Windshield	Chipped	Repair	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.