Approved CR

Dealers Auto Auction of Cincinnati, LLC
120 City Centre Drive
Cincinnati, OH 45216
513-679-7910/513-679-7913
aschoenling@dealersauto.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 CHEVROLET SILVERADO 3500HD WOR**
Bodystyle/Series:	**Crew Cab -**
Color:	**GRAY**
Mileage:	**42,638 (Digital)**
Turn-in Mileage:	-
VIN:	**1GC4KYCG7HF192299**
Work Order/ Stock Number:	**0051414**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**102620I2192299**
Vehicle Grade :	**Grade 2.4**
Remarks:	-
Announcements:	• RIDE & DRIVE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment


Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

Auxiliary Audio Input	Backup camera and monitor	Bluetooth Connection
Car Jack	Car LF Tires - 14/32 inch	Car LR Tires - 14/32 inch
Car RF Tires - 14/32 inch	Car RR Tires - 14/32 inch	Car Tire Size - LF: LT265/70R18E LR: LT265/70R18E RF: LT265/70R18E RR: LT265/70R18E SP: FULL SIZE
Cylinders - 8	Daytime Running Lights	Driver Adjustable Lumbar
Driver Restriction Features	Electronic Stability Control	Front Tow Hooks
Hand Tool Kit	Ignition Key - 2key(s)	LF Tires - 14/32 inch
LR Tires - 14/32 inch	Limited Slip Differential	MP3 Radio
Misc. Special Features - Airbag Disconnect Switch	Pass-Through Rear Seat	Pass. Air Bag
RF Tires - 14/32 inch	RR Tires - 14/32 inch	Rear Bench Seat
Smart Device Integration	Spare Tire - Full Size	Spare Tire Brand - GOODYEAR
Spare Tire Tread - 14/32 inch	Spare Wheel - Steel	Tilt Steering Wheel
Tire Brand - Front Left - COOPER	Tire Brand - Front Right - COOPER	Tire Brand - Rear Left - COOPER
Tire Brand - Rear Right - COOPER	Tire LF - 14/32 inch	Tire RF - 14/32 inch
Tire Size - LF: LT265/70R18E LR: LT265/70R18E RF: LT265/70R18E RR: LT265/70R18E SP: FULL SIZE	Tire Size - LF: LT265/70R18E LR: LT265/70R18E RF: LT265/70R18E RR: LT265/70R18E SP: FULL SIZE	Tow Hitch
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Chargeable Damages

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door Panel	Stained	Detail	Permanent
	Cushion Center Rear	Stained	Detail	Permanent
	Left Rear Seat Cushion	Stained	Detail	Permanent
	Left Front Door	Multiple Dents/Paint Damage	Repair	4
	Left Bed Side	Multiple Dents/Paint Damage	Repair	10 Or More
	Cab - Left	Multiple Scratches Heavy	Touch Up	3
	Left Rear Door	Chipped	Touch Up	2
[no photo]	Jack Assembly (Lugg. Comp.)	Missing	Replace	Replacement Required
	Pickup Bed	Multiple Scratches Light	Touch Up	10 Or More
	Tailgate	Multiple Dents/Paint Damage	Repair	10 Or More
[no photo]	Tools	Missing	Replace	Replacement Required
	Right Cab Side	Multiple Dents/Paint Damage	Repair	4
	Right Bed Side	Multiple Dents/Paint Damage	Repair	10 Or More
	Right Rear Door	Chipped	Touch Up	1

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Dent(S) W/ Paint Dmg	Repair	< 1/8 Inch
	Front Center Armrest	Stained	Detail	Permanent
	Headlining	Stained	Detail	Permanent
	Hood	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
[no photo]	Windshield	Replaced	-	Acceptable
	Overhead Console	Stained	Detail	Permanent
	Left Front Seat	Stained	Detail	Permanent
	Right Front Seat	Stained	Detail	Permanent
	Left Front Seat Back	Stained	Detail	Permanent
	Right Front Seat Back	Stained	Detail	Permanent
	Right Rear Seat Cushion	Stained	Detail	Permanent
[no photo]	Right Front Speaker	Broken	Mechanical Check	Replacement Required
	Left Sunvisor	Stained	Detail	Permanent
	Right Sunvisor	Stained	Detail	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.