



Approved CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 BLUE BIRD SCHOOL BUS / TRANSIT BUS**

Bodystyle/Series: - -

Color: **White**

Mileage: **73,823 (Verified)**

Turn-in Mileage: -

VIN: **1BABLCPA7GF320255**

Work Order/
Stock Number: **46299884**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G32A0547**

Vehicle Grade : **Grade 2.9**

Remarks: -

Announcements: -

Certification : -

Req. Prev. Repair -

Order:



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	No
Engine Size:	6.7 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- / -	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-
Additional Equipment:	-		

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	6
	Rear Rs Panel Extension	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Right Rear Seat Back	Torn	-	5 To 6 Inches
	Left Rear Seat Back	Torn	-	7 To 8 Inches
	3rd Row Seat Center Back	Torn	-	3 To 4 Inches
	Corner Panel	Multiple Dents/Paint Damage	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.