



Approved CR

IAA Indianapolis
3302 South Harding Street
Branch No 541
Indianapolis, IN 46217
(317) 787-3202/(317)783-0586
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
F-250**
Bodystyle/Series: **Crew Cab XL**
Color: **White**
Mileage: **21,224
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT7W2B65KEC55792**
Work Order/
Stock Number: **46373568**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G630013X**
Vehicle Grade : **Grade 3.5**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Sport	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 35 / 12.50 R 17	Car Tire Size - RR 35 / 12.50 R 17	Car Tire Size - LF 35 / 12.50 R 17
Car Tire Size - RF 35 / 12.50 R 17	LF Tires - 13/32 inch	LR Tires - 14/32 inch
RF Tires - 14/32 inch	RR Tires - 12/32 inch	Tire Brand - Front Left - MUD CLAW
Tire Brand - Front Right - MUD CLAW	Tire Brand - Rear Left - MUD CLAW	Tire Brand - Rear Right - MUD CLAW
Tire Model - LF - Mud Claw Comp MTX	Tire Model - LR - Mud Claw Comp MTX	Tire Model - RF - Mud Claw Comp MTX
Tire Model - RR - Mud Claw Comp MTX		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Warning Light - Air Bag	On	-	Unacceptable
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Right Rear Seat Cushion	Stained	-	Permanent
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch
	Right Bed Side	Heavy Scratch	-	1/2 To 1 Inch
	Right Front Fender	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.