



Approved CR

IAA Las Vegas
3225 South Hollywood Blvd
Branch No 152
Las Vegas, NV 89122
(702) 565-8795/(702) 564-6553
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
FUSION
HYBRID**

Bodystyle/Series: **4 Door Sedan
S**

Color: **White**

Mileage: **66,066
(Verified)**

Turn-in Mileage: **-**

VIN: **3FA6P0UUXJR279001**

Work Order/
Stock Number: **46373728**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G102181V**

Vehicle Grade : **Grade 3.9**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 50 R 17	Car Tire Size - RF 225 / 50 R 17	Car Tire Size - LF 225 / 50 R 17
Car Tire Size - LR 225 / 50 R 17	LF Tires - 11/32 inch	LR Tires - 11/32 inch
RF Tires - 9/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - BIG O
Tire Brand - Front Right - BIG O	Tire Brand - Rear Left - BIG O	Tire Brand - Rear Right - BIG O
Tire Model - LF - legacy all season plus	Tire Model - LR - legacy all season plus	Tire Model - RF - legacy all season plus
Tire Model - RR - legacy all season plus		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Windshield	Multiple Chips	-	5
	Left Front Wheel	Curb Rash	-	4 To 5 Inches
	Left Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Deck Lid	Chipped	-	2
	Rear Bumper	Chipped	-	2
	Right Rear Wheel	Curb Rash	-	7 To 8 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	9 To 10 Inches
	Front Bumper	Chipped	-	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.