



Approved CR

IAA Eugene
1000 Bethel Drive
Branch No 309
Eugene, OR 97402
(541) 689-4000/(541) 689-0083
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
F-150**
Bodystyle/Series: **Extended Cab
XLT**
Color: **Silver**
Mileage: **96,327
(Verified)**
Turn-in Mileage: **-**
VIN: **1FTFX1E55KKE23406**
Work Order/
Stock Number: **46374738**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G624449W**
Vehicle Grade : **Grade 3.1**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 65 R 18

Car Tire Size - LR 275 / 65 R 18

Car Tire Size - RR 275 / 65 R 18

Car Tire Size - RF 275 / 65 R 18

LF Tires - 7/32 inch

LR Tires - 12/32 inch

RF Tires - 6/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Destination X/T

Tire Model - RF - Destination X/T


Tire Model - LR - Destination X/T

Tire Model - LF - Destination X/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Keys	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	9 To 10 Inches
	Right Bed Side	Chipped	-	3
	Right Rear Wheel	Curb Rash	-	> 12 Inches
	Tailgate	Multiple Dents/Paint Damage	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Left Rear Wheel	Curb Rash	-	9 To 10 Inches
	Left Front Wheel	Curb Rash	-	> 12 Inches
	Front Bumper Cover Upper	Scraped	-	7 To 8 Inches
	Front Metal Bumper Chrome	Heavy Scratch	-	4 To 5 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Cab Side	Multiple Scratches Light	-	3
	Right Front Door	Chipped	-	2
	Right Rear Door	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.